

1. DESCRIPTION OF WORKS AND PHOTOGRAPHIC REPORT

Listed below are all the works carried out by **3RS GESTIÓN** for the Urban Solid Waste Collection Service, Street Cleaning and Maintenance of the Green Areas of the urban entity "Hacienda del Álamo Golf Resort", in **OCTOBER 2026**.

1.1. MUNICIPAL SOLID WASTE WORKS

ACT OF VANDALISM: Dumping of construction debris (surplus building materials, specifically tiles) next to the waste container located at 7 Madagascar, in El Oasis. The EUC has been notified.



INCIDENT: Dumping of construction debris (specifically a toilet and a bidet) next to the waste containers located on Georgia Street in Los Olivos. The EUC has been notified.



1.2. STREET CLEANING WORKS

Resolution of an INCIDENT involving debris washed down to the end of Letonia Street due to recent torrential rains.



1.3. GARDENING WORKS

Trimming of hedges and ornamental ficus trees, weeding, and clearing along the Main Road






Mowing the driveway lawn, the square garden, the driveway roundabout, the Phase 6 roundabout, and the Phase 1 roundabout



Pruning of palm trees under 3m in the Cortinas Verdes garden, around the Black Gravel Roundabout



Weeding and cleaning in the area opposite the Maintenance Zone, on Vistas al Green Street and Lago Street





Pruning and cleaning of fan palms at the roundabout outside the entrance to the residential development



Hedge trimming and pruning of fan palms in the median and exterior garden beds at the entrance to the residential development



Weeding and cleaning on Japón Street (Non-residential sector)





Trimming of hedges and ornamental ficus trees, brush clearing, and cleanup on Bélgica Avenue (Phase 2-3)



Trimming of hedges and ornamental ficus trees, brush clearing, and cleanup on Bahamas Street (Phase 2-3)



**Trimming of hedges and ornamental ficus trees, brush clearing, and cleanup along
Road B, from El Oasis to Phase 1**






Pruning of suckers on the olive trees on Georgia Street, Phase 6



Pruning of shrubs, manual weeding, and cleaning of the median strip on Calabardina Street (Pueblo Español)





Phytosanitary treatments against the date palm weevil in private residences



Review of the irrigation network, opening manholes and checking controllers, solenoid valves, and emission points, detecting and repairing each of the incidents detected at the following locations:



Bélgica Ave. - Left side of entrance (repair of 0.5 m of PE, Ø16, 1 link)



Phase 6 - Guinea St., Algarrobos garden (repair of 2 lm of Ø32 PE, 2 links)



Phase 6 - Olivos B (repair 0.5 lm PE Ø32, 2 links)



Phase 6 - Olivos B (repair 0.5 lm PE Ø32, 2 links)



Phase 6 - Olivos B (repair 0.5 lm PE Ø32, 2 links)



Phase 6 - Olivos B (repair 0.5 lm PE Ø32, 2 links)



Entrance - Roundabout (repair 0.5 ml PE Ø50, 1 elbow)



Entrance - Roundabout (repair 0.5 ml PE Ø50, 1 elbow)



Phase 6 - Olivos A (repair 0.5 m of PE Ø32; 2 links)



Phase 6 - Olivos A (repair 0.5 m of PE Ø32; 2 links)



Pueblo Español - Garden/pool area (repair 1 lm PE Ø32, 2 links)



Pueblo Español - Garden/pool area (repair 1 lm PE Ø32, 2 links)