

1. DESCRIPTION OF WORKS AND PHOTOGRAPHIC REPORT

Listed below are all the works carried out by **3RS GESTIÓN** for the Urban Solid Waste Collection Service, Street Cleaning and Maintenance of the Green Areas of the urban entity "Hacienda del Álamo Golf Resort", in **MARCH 2026**.

1.1. MUNICIPAL SOLID WASTE WORKS

Resolution of **VANDALISM ACT** due to the appearance of pruning remains at C/ Alemania, 89. The EUC and **SECURITY** have been informed.



Resolution of VANDAL ACT due to the appearance of a large quantity of cardboard in the waste container, at C/ Brasil, 16. The EUC and SECURITY have been informed.



1.2. STREET CLEANING WORKS

Cleaning and disinfection work on sidewalks, roads and drains of Italia, Irlanda and Islandia streets, following the clearing and chemical weeding work:



C/ Italia



C/ Italia



C/ Italia



C/ Italia

1.3. GARDENING WORKS

Weeding and trimming of hedges along road B, between sectors C/ Hungría and C/ Francia



Weeding and cleaning of the elongated garden “Paseo por Paisajes” of Vial B, between sectors C/ Hungría and C/ Francia




Mowing of the lawn at the entrance, the square garden, the entrance roundabout, the Phase 6 roundabout and the Phase 1 roundabout:



Tree pruning and cleaning in Plaza Australia (Phase 1):



Weeding and trimming of hedges along road B, between sectors C/ Francia and C/ Japón



Tree pruning and cleaning in Plaza Alemania (Phase 1):



Tree pruning, shrub trimming and cleaning at the roundabout on C/ Alemania (Phase 1):



Weeding and trimming of hedges along road B, between the C/ Japón and New Construction Roundabout:








Tree pruning and cleaning in “Jardín del Borde”, behind Phase 1 Los Olivos:



Tree pruning, shrub trimming and cleaning in roundabouts C/ Bahamas and C/ Brasil (Phases 2 and 3):



Weeding, trimming of alignment hedges and cleaning in Paseo Alameda of Phase 7 Oasis:




Mowing of the lawn at the entrance, the square garden, the entrance roundabout, the Phase 6 roundabout and the Phase 1 roundabout:




Planting of 60 Unit. *Cupressus sempervirens* 'totem' trees, 3 meters tall, in the flowerbed to the right of the entrance, including replacement of the irrigation system:




Manual and mechanical weeding of sidewalks and curbs in Phases 4 and 5:



Manual and mechanical weeding of sidewalks and curbs in Phases 2 and 3:






Manual clearing and cleaning of gravel flowerbeds at the entrance (roundabout and fountain):



Incident resolution reported by SECURITY, regarding the removal of ficus trees on the left side of the Main Road, opposite the Golf Club promenade (EUC have been informed):



Review of the irrigation network, opening manholes and checking controllers, solenoid valves, and emission points, detecting and repairing each of the incidents detected at the following locations:



**Phase 2 - In front of C/ Brasil, 30
(programmer battery change)**



**Phase 6 - Front Garden (20 ml PE Ø32 and 2
links)**



**Phase 6 - Front Garden (20 ml PE Ø32 and 2
links)**



**Phase 6 - Front Garden (20 ml PE Ø32 and 2
links)**



**Phase 7 Oasis - Right hedge (2 ml PE Ø16
and 2 links)**



**Phase 7 Oasis - Paseo Alameda and Round.
(215 ml PE Ø16 and 80 punctured droppers)**



**Phase 7 Oasis - Paseo Alameda and Round.
(215 ml PE Ø16 and 80 punctured droppers)**



**Phase 7 Oasis - Paseo Alameda and Round.
(215 ml PE Ø16 and 80 punctured droppers)**



**Garden Pictures - Vandalism: 2 programmers
ripped out (Rain Bird programmer replaced
with Solem)**



**Garden Pictures - Vandalism: 2 programmers
ripped out (Rain Bird programmer replaced
with Solem)**



**Garden Pictures - Vandalism: 2 programmers
ripped out (Rain Bird programmer replaced
with Solem)**



**Garden Pictures - Vandalism: 2 programmers
ripped out (Rain Bird programmer replaced
with Solem)**



Garden Pictures - Drip line replacement (180 ml PE Ø16, 36 links and 1 Solem 1E programmer)



Garden Pictures - Drip line replacement (180 ml PE Ø16, 36 links and 1 Solem 1E programmer)



Garden Pictures - Drip line replacement (180 ml PE Ø16, 36 links and 1 Solem 1E programmer)



Garden Pictures - Drip line replacement (180 ml PE Ø16, 36 links and 1 Solem 1E programmer)



Phase 7 Oasis - Drip line replacement (485 ml PE Ø16, 12 links and 20 droppers)



Phase 7 Oasis - Drip line replacement (485 ml PE Ø16, 12 links and 20 droppers)



Phase 7 Oasis - Drip line replacement (485 ml PE Ø16, 12 links and 20 droppers)



Phase 7 Oasis - Drip line replacement (485 ml PE Ø16, 12 links and 20 droppers)



Phase 8 Pueblo Español - Replacement of right drip line (40 ml PE Ø16 and 4 links)



Right entrance - Cypress hedge alignment Totem (60 trees, irrigation setback, 6 diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links Ø32, 42 ml PE Ø16, 1 Solem 1E programmer, 1 solenoid valve and 1 valve box)



Right entrance - Cypress hedge alignment Totem (60 trees, irrigation setback, 6 diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links Ø32, 42 ml PE Ø16, 1 Solem 1E programmer, 1 solenoid valve and 1 valve box)



Right entrance - Cypress hedge alignment Totem (60 trees, irrigation setback, 6 diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links Ø32, 42 ml PE Ø16, 1 Solem 1E programmer, 1 solenoid valve and 1 valve box)



**Right entrance - Cypress hedge alignment
Totem (60 trees, irrigation setback, 6
diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links
Ø32, 42 ml PE Ø16, 1 Solem 1E programmer,
1 solenoid valve and 1 valve box)**



**Right entrance - Cypress hedge alignment
Totem (60 trees, irrigation setback, 6
diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links
Ø32, 42 ml PE Ø16, 1 Solem 1E programmer,
1 solenoid valve and 1 valve box)**



**Right entrance - Cypress hedge alignment
Totem (60 trees, irrigation setback, 6
diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links
Ø32, 42 ml PE Ø16, 1 Solem 1E programmer,
1 solenoid valve and 1 valve box)**



**Right entrance - Cypress hedge alignment
Totem (60 trees, irrigation setback, 6
diffusers, 30 ml PE Ø32, 1 valve Ø32, 4 links
Ø32, 42 ml PE Ø16, 1 Solem 1E programmer,
1 solenoid valve and 1 valve box)**



**Main Road Median - Next to Storage Area (1.5
ml PE Ø32 and 2 links)**



**Phase 1 - Replacement in P. Alameda Right
(265 ml PE Ø16 and 9 links)**



**Phase 1 - Replacement in P. Alameda Right
(265 ml PE Ø16 and 9 links)**



**Phase 1 - Replacement in P. Alameda Right
(265 ml PE Ø16 and 9 links)**



**Phase 1 - Replenishment Australia (35 ml PE
Ø16, 4 links and 1 Solem 1E programmer)**



**Phase 1 - Replenishment Australia (35 ml PE
Ø16, 4 links and 1 Solem 1E programmer)**



**Garden Pictures - Next to Mailboxes Phase 6
Olive Trees (replacing broken Rain Bird
programmer with 1 Solem 2E)**



**Garden Pictures - Next to Mailboxes Phase 6
Olive Trees (replacing broken Rain Bird
programmer with 1 Solem 2E)**



Entrance Fountain - Cleaning leaf accumulation in pump and floating area



Phase 7 Oasis - Leakage due to root constriction in front of new apartments (1.5 ml PE Ø32 and 2 links)