


1. DESCRIPTION OF WORKS AND PHOTOGRAPHIC REPORT



Listed below are all the works carried out by **3RS GESTIÓN** for the Urban Solid Waste Collection Service, Street Cleaning and Maintenance of the Green Areas of the urban entity "Hacienda del Álamo Golf Resort", in **FEBRUARY 2026**.

1.1. GARDENING WORKS

Weeding and trimming of hedges along road B, between sectors C/ Hungría and C/ Francia







Cutting, collecting and cleaning of a tree (false pepper tree) fallen by the wind on Vial B at the height of C/ Francia



Cutting, collecting and cleaning of a tree (pine) fallen by the wind on Vial B at the Alemania Place



Trimming of evergreen hedge on Main Road, section from entrance to Phase 6 The Olives



Trimming, collecting and cleaning of garden hedges of squares and laurel screen hedge



Weeding and cleaning of the slope and fence area next to the cul-de-sac of C/ Vistas al Green






Hedge trimming, weeding and cleaning in the right-hand area of the entrance to the Maintenance Zone



Manual weeding at the entrance roundabout of the Casa Club on the main road



Pruning and cleaning of palm trees in the left garden at the entrance to the Maintenance Zone




Mowing of the lawn at the entrance, the square garden, the entrance roundabout, the Phase 6 roundabout and the Phase 1 roundabout:




At the request of the EUC, the weeding and cleaning of C/ Morella, between Pueblo Español and the Golf Course, is being carried out



Cutting, collecting and cleaning fallen trees in Rambla Mediterránea Park (a pine branch and a 6-meter cypress)



At the request of the EUC, the weeding and cleaning of the path that connects Canada Street and the Golf Academy parking, is being carried out





Review of the irrigation network, opening manholes and checking controllers, solenoid valves, and emission points, detecting and repairing each of the incidents detected at the following locations:



**Brasil St., 30 - Roundabout garden
(programmer battery replacement)**



**Entrance Fountain - Legionella control
(emptying, cleaning with brush and pressure
washer, disinfection and filling; sampling
after 15 days)**



Bélgica St., 29 (3 ml PE Ø32 y 2 links)



Bélgica St., 29 (3 ml PE Ø32 y 2 links)



Main road both sides - From Phase 1 roundabout to Phase 6 roundabout (950 ml PE Ø16 and 10 links)



Main road both sides - From Phase 1 roundabout to Phase 6 roundabout (950 ml PE Ø16 and 10 links)



Entrance Fountain - New installation (new valve box, 1" solenoid valve and Solem 1E programmer)



Entrance Fountain - New installation (new valve box, 1" solenoid valve and Solem 1E programmer)



Main Road median (20 ml PE Ø16 and 2 links)




Main Road median (20 ml PE Ø16 and 2 links)



Main road median - in front of Hotel (Rain Bird programmer replaced with Solem 2E)



Main road median - in front of Hotel (Rain Bird programmer replaced with Solem 2E)



Entrance Fountain - Cleaning due to accumulation of solid waste in hydraulic body nozzle



Entrance Fountain - Cleaning due to accumulation of solid waste in hydraulic body nozzle



Entrance Fountain - Cleaning due to accumulation of solid waste in hydraulic body nozzle



Entrance Fountain - Cleaning due to accumulation of solid waste in hydraulic body nozzle